

## Technical Information:

**Date:** June 01 2004  
**Subject:** Design Change To New Flow Sensors  
**Product:** Size I and Size II Flow Sensors  
**Category:** GALA Accessory  
**Page :** 1 Page

A design change has been made to the new style Size I and Size II flow sensors to eliminate the potential problem of the upper magnet of the sensor coming out of its location. This change is already standard on new units.

If you come across anyone experiencing this problem we are offering a conversion kit to this new design. We have the kits on order and are expecting them here shortly.

Conversion Kit Size I Part # 1024548  
Conversion Kit Size II Part # 1024547

This kit includes all the parts necessary and can easily be retrofitted.

The part # of the sensors has not changed.

If you have any questions or comments on this change, please contact the Technical Dept.